## FITNESS

To be filled by the Inspecting Officer (Asst. Engineer) (Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970) .

		TWIN GODWIN DSILVA
1,	Name of the Officer	TOTAL STORY OF THE
2.	Name of the School	VIVEKODAYAM VIDYA MANDIR
3	Location with name of Education District/ Sub. District	ANNAMANADA, IRINJALAKUDA
4.	Classification of Building as specified in column 4 of the application for fitness certificate and size.	Permanent
		56.80x 7.10x 3.60 (9 moms)
		CB(dg NO: V 13A)
_		
5.	Period for which the certificate is issued	2022 June - 2023 March
6.	Nature of defects , if any	
	a) Foundation and basement	
	b) Superstructure	
	c) Doors and Windows	
	d) Wood work wrought and put up	
	el Roof	> Neel
	1) Flooring	
	g) Miscellaneous (Cracks, etc.)	
7	Any major defects noticed which will render the building unsafe in any manner	
8	Whether maintenance works have been done properly	go und under not mal wind & weather
<b>.</b>	Whether the structure is sound or not for conducting classes	F71/1 1 3 A F 3/L
1	Note: 1. The stability of the structure should be examined also exposure of flood etc. 2. Any additional observations if deen separately with this certificate.	med necessary for the certificate may be furnished
	<b>N</b>	
	CERTIFICA	ATE
	certified that the school building was inspected by me or	30 5 2029 and
form	d to be fit /unfit to conduct classes, for the period	de normal wild of weather the
loui	ons stated above	Conditions
reas	ons stated above	स्वयास्त्रीय के स्थाप (क्ष्मिक्षीय एक्स) । १८४५ वि
	A	
Plac	e duna manada	
Date	e Annamanada 3.15/2022 (Seal)	A. w.d
2000	Assistant Engi	a with
	ce in the	Assistant Engineer
sian sian	LSGD Section LSGD Section	riveltodayam Vidya Mandir Annamanada ASSISTANT ENGINEER
Λ,	Sancia M.	rivelodayam Vidya ASSISTANT ENGINEER
101	LSGD Section LSGD Section For Managed Grama Pantina	MA DELLEGISTON
1	THE WAY OF A WAY THE WAY	THRISSUR DIST
	The state of the s	The state of the s